

CZ Peep Sight instructions:

Ghost ring peep sights for the CZ 550 and 527 actions

All steel and made in the USA. Fully adjustable for windage and elevation.
No gunsmithing required.

Installation: To attach the sight, first position the sight on the rear bridge. Align the recoil lug with the notch found on the CZ rear bridge, then hand tighten the knurled knob on the right side.

To adjust elevation: First, loosen the small set screw on the front (muzzle end) of the sight body by two or three turns with the enclosed wrench. To **raise** the point of impact, turn the aperture in a **counterclockwise** direction. To **lower** the point of impact, turn the aperture **clockwise**. Please note that each half turn equals one inch of correction at 100 yards based on a 25" barrel. Tighten the set screw to lock the aperture stem.

To adjust windage: Loosen the small set screw on the rear end of the left clamp by two or three turns with the enclosed wrench. (**Do not** loosen the set screw in the middle of the sight body) To move the point of impact to the **left**, loosen the right knurled knob and tighten the left knob. To move the point of impact to the **right**, loosen the left knurled knob and tighten the right knob. Tighten knobs with a coin after last adjustment and then tighten the set screw on left clamp. Peep sight will return to zero. **Do not over-tighten!**